






| A | B | C | | D |
|----|---------|------|-----|-----|
| 1 | NT1-792 | 1860 | 842 | 2/4 |
| 2 | NT1-793 | 1860 | 387 | 2/4 |
| 3 | NT1-035 | 1723 | 386 | 1/4 |
| 4 | NT1-148 | 1803 | 200 | 3/4 |
| 5 | NT1-126 | 2000 | 250 | 3/4 |
| 6 | NT1-538 | 1894 | 80 | 3/4 |
| 7 | NT1-539 | 1894 | 80 | 3/4 |
| 8 | NT1-521 | 386 | 68 | 4/4 |
| 9 | NT1-522 | 486 | 68 | 4/4 |
| 10 | NT1-570 | 350 | 92 | 4/4 |





| | | | | | | | |
|-------------------------------|-----------------------------|------------------------------|------------------------------|------------------------------|-----------------|-----------------------------------|---------------------------------|
| 16x Ø6,3x13mm e2 | 4x Ø7x60 mm e8 | 24x Ø7x28mm e22 | 10x φ8x30 mm f1 | 16x φ8x50 mm f6 | 9x k1 | 2x 130x34x34/2mm n63 | 8x φ15x12mm #16 r1 |
| 8x 20/11 r42 | 4x r5/1 | 4x Ø6x54mm r5/2 | 19x s1 | 1x Клей y1 | 1x z1 | | |






5



6



7

