




# ТВІСТ / ТВИСТ

# Надставка

A	B	C		D
1	S49-007	510	396	2/2
2	S49-106	1002	285	1/2
3	S49-107	1002	285	1/2
4	S49-110	482	285	1/2
5	S49-114-01	146	187	2/2
6	S49-308	1167	285	1/2
7	S49-309	1167	285	1/2
8	S49-315	783	285	1/2
9	S49-316	368	285	1/2
10	S49-317-01	308	187	2/2
11	S49-409	1167	80	1/2
12	S49-410-01	308	308	2/2
13	S49-905-01	1194	503	1/2
14	S49-906-01	1194	491	1/2



2x  <b>a44</b>	2x  <b>b19</b>	1x  <b>c176/1</b>	4x  φ5x17 mm <b>d1</b>	18x  φ7x50 mm <b>e1</b>	8x  φ5x50 mm <b>e32</b>	10x  φ8x30 mm <b>f1</b>	2x  φ6x50 mm <b>f36</b>
60x  <b>l1</b>	1x  <b>n2611</b>	2x  62x12/1mm <b>n52</b>	1x  φ4x30 mm <b>p9</b>	6x  φ3,5x16 mm <b>p25</b>	7x  φ3,5x16 mm <b>p38</b>	4x  φ3,5x15 mm <b>p51</b>	18x  <b>s1</b>
1x  <b>z1</b>							

